

AA Composites - 0444568646

Low Bubble Instructions & Info

2:1 by Weight

Low Bubble is our cheapest resin available however it is also one of our top selling, it is a great multipurpose resin. When pouring shallow pours it is extremely clear, the deeper pours can yellow this resin but if mixing with pigment it is perfect..

Mix 2 parts A to 1 Part B by weight. Mix resin and hardener together, the resin will go cloudy - keep mixing until resin goes back to clear *always mix by hand*. Make sure all of the product has been mixed, including scraping the sides of the mixing container. Pour resin and allow to cure.

Depth of Resin: Low Bubble can be coated or poured up to 40mm

Setting time of Resin: Working time: 45 Minutes
Initial Cure: 12 Hours
Full Cure: 3 Days

*Please note that the resin times are based on 25°C lab tested results and will vary on depth of pour and temperature.

Resin will not set below 10°C, and will take longer in a cooler environment, make sure on cooler days that the resin is in the sun or near heat, you can warm the bottles in hot tap water before pouring to allow the resin to heat up a bit.